

Kennecott Barneys Canyon Mining Company  
P.O. Box 311  
8200 South 9600 West  
Bingham Canyon, Utah 84006-0311  
T 801-569-7000  
F 801-569-7190

Steve Schnoor  
Manager – Environmental, Land and Energy

October 9, 2015

Mr. Paul Baker, Minerals Program Manager  
Division of Oil, Gas & Mining  
Utah Department of Natural Resources  
1597 West North Temple, Suite 1210  
P.O. Box 145801  
Salt Lake City, Utah 84114-5801

RECEIVED

OCT 08 2015

Div. of Oil, Gas & Mining


Subject: **Barneys Canyon Mine Request to Review Heap Leach Pads #1 thru #4  
Buttress Request for Approval to Construct Supporting Documents**

Dear Mr. Baker:

In reference to a September 21, 2015 submittal sent to the Utah Department of Environmental Quality, Division of Water Quality that the Division of Oil, Gas & Mining was copied on and received September 22, 2015, titled *Request for Approval to Construct, Barneys Canyon Mine Heap Leach Pads #1 thru #4 Buttress, Groundwater Discharge Permit No. UGW350001*, please formerly review the submittal documents as applicable per Rule R647 of the Utah Administrative Code.

Should the division have any questions regarding this submittal or require additional information during the review, please contact Thiess Lindsay at 801.569.6066.

Regards,



Steve Schnoor  
Manager - Environment, Land and Energy  
Rio Tinto Kennecott  
For: Barneys Canyon Mining Company

cc: Leslie Heppler (UDOGM)  
Mike Bradley (UDOGM))  
Peter Brinton (UDOGM)

M1035/0009  
6915



bcc: B. Vinton  
T. Lindsay  
T. Heaton  
J. Bradt  
T. Nannini  
File: OPS/GW/Barneys/Notifications